
Drawings

SD 01C25W04-01EN

EJXC50A, EJAC50E Direct Mounted Diaphragm Seal System EJX530A and EJA530E Gauge Pressure Transmitter Process Connections Code P




Unit: mm (approx. inch)



• With Process connections code P

*1: When electrical connection code 7 or C is selected, a blind plug is protruded up to 8 mm from the conduit connection.

• Terminal Configuration



• Terminal Wiring

SUPPLY	+ _	$\begin{bmatrix} 1\\ 2 \end{bmatrix}$ Power supply and output terminals
CHECK	+ -	$\begin{array}{c} (3) \\ (2) \end{array}$ External indicator (ammeter) terminals ^{*1*2} or
ALARM	+ -	$\begin{array}{c} (3) \\ (2) \end{array}$ Status contact output terminals ^{*2} (when /AL is specified)
Ground terminal		

*1: When using an external indicator or check meter, the internal resistance must be 10 Ω or less. A check meter or indicator cannot be connected when /AL option is specified.

*2: Not available for FOUNDATION Fieldbus and PROFIBUS PA communication types.

